

EASA.AP175

Doc.: SB-MD01-001-R00

Date: 15.11.2018 **Page:** 1 of 5

Mandatory Service Bulletin

SB-MD01-001

Rev. 00

1 Technical Details

1.A Category

Mandatory

1.B Subject

Jet System Engine Wiring Loom Damage Inspection and Repair

1.C Affected

Type: JS-MD Single Model: JS-MD 1C MSN: all

with Jet Engine MD-TJ42 installed

1.D Reason

Due to chafing of the jet system wiring loom by souring of the pylon smouldering might occur.

1.E Time of Compliance

Action 1 Within the next **30 calendar days** or **5 engine cycles**, whichever comes first

Action 2 with **next annual inspection** installation of the protective sleeving

Action 3 replacement of damaged wiring loom and installation of protective sleeving

Action 4 every **25 flight hours**

1.F Reference

M&D work instruction WI-SB-MD01-001.

1.G Mass and CG

No change in mass and CG.



EASA.AP175

Doc.: SB-MD01-001-R00

Date: 15.11.2018 **Page:** 2 von 5

1.H Actions
Action 1:
Within the next 30 calendar days or 5 engine cycles, whichever comes first, perform visual inspection of the wiring on the jet pylon, see Appendix I.
If the wiring is found serviceable , see action 4.
If the wiring is found damaged during visual inspection, perform action 3.
Action 2:
If the wiring of the jet system wiring loom is serviceable , a protective sleeving must be installed with the next annual inspection .
The installation of the protective sleeving must be performed according to working instruction WI-SB-MD01-001 Action 1.
Action 3:
If the wiring of the jet system wiring loom is damaged, the wiring loom has to be replaced.
The replacement of the wiring loom must be performed according to working instruction WI-SB-MD01-001 Action 2.
Action 4:
Every 25 flight hours perform visual inspection of the wiring on the jet pylon until next annual inspection.
With next annual inspection perform action 2.
If the wiring is found damaged during visual inspection, perform action 3.



EASA.AP175

Doc.: SB-MD01-001-R00

Date: 15.11.2018 **Page:** 3 von 5

1.I Interchangeability and Mixability of Parts

None.

1.J Approval

The technical content of this document is approved under the authority of APDOA ref. EASA.AP175.

1.K Appendices

Appendix – Inspection

The appendix provides the instructions and inspection points to perform on the aircraft.

2 Planning Information

2.A Material

All standard parts according to work instruction WI-SB-MD01-001 can be ordered from the following company or a local supplier.

All non-standard parts according to WI-SB-MD01-001 must be ordered specifying this SB No. from the following company:

M&D Flugzeugbau GmbH & Co. KG Streeker Straße 5b 26446 Friedeburg

> info@md-flugzeugbau.de +49 (0) 4465 978 78 11

2.B Tools

All special tools according to work instruction WI-SB-MD01-001 must be ordered specifying this SB No. from the following company:

M&D Flugzeugbau GmbH & Co. KG Streeker Straße 5b 26446 Friedeburg

> info@md-flugzeugbau.de +49 (0) 4465 978 78 11



Service Bulletin EASA.AP175

Doc.: SB-MD01-001-R00 Date: 15.11.2018

Page: 4 von 5

3 Remarks

Action 1 and Action 4 can be performed and released by the pilot / owner in accordance with EASA Part M paragraph M.A.803(b) (see Appendix).

Action 2 and Action 3 needs to be performed and released:

- by maintenance organisations approved in accordance with EASA Part-145 and with appropriate rating;
- by maintenance organisations approved in accordance with EASA Part-M Subpart F and with appropriate rating;
- in accordance with M.A.801 c) and f) outside approved maintenance organisations by independent certified staff in accordance with Part-66.

4 Approval Signatures

Remark: With the signature, the **HoAO** confirms that the technical content of the Service Bulletin has been checked, and the change described is approved.

Date:	Approved by EASA	
(Head of Airworthiness Office)	on: 29.11.2019 under approval No.: 10071845	(if applicable)
	Initial Issue	



EASA.AP175

Doc.: SB-MD01-001-R00 **Date:** 15.11.2018

Page: 5 of 5

Appendix - Inspection

Within the **next 30 calendar days** or **5 engine cycles** whichever comes first, perform visual inspection of the wiring on the jet pylon according to following instructions:

- Drive the engine half-way out by using the maintenance mode of the Engine-Display-Unit
- Disconnect the engine LH and RH bay-doors
- With a pen, mark the position of the pylon fairing to the pylon
- Unfasten (not entirely!) LH and RH the screws of the pylon fairing
- Move the pylon fairing downwards

Perform visual inspection. The damage can be seen in Figure A-1.




Figure A-1: Wiring Damage, pylon fairing moved downwards

Whether the wiring is serviceable or damaged retract the engine again. Therefore perform the above mentioned steps in reversed order.

- Extent the engine normally
- Check if pylon fairing stayed in its correct position (marking)
- If NO: the pylon fairing needs to be re-adjusted
- If **YES**: the work is completed
- Release the aircraft according to EASA Part M paragraph M.A.803(b).